

CAM Basics 1.2 - Tool controls

Run through of tool path windows and their controls

Written By: Christopher James Hostetler



Step 1 — Operations



- Milling operations are located here
- 2D milling focus on 1 z axis level at a time.
- 3D milling tool will move in all 3 axis

Step 2 — Tool Tabs

Ⅲ ■ * 四 ちょう*	🗊 Yoke -	Topology (1) v2 × + 🧟 🌒 1	Christopher Hostetler	III 📑 * 🗒 ちょみょ	🗊 Yoke -	Topology (1) v2 ×	+ 🤦 🕲 1 Christopher Hostetler	0
MANUFACTURE • SETUP • 20 •	ADDITIVE PROI	RAGICATION UTLITES		MANUFACTURE + SETUP + 20 +	ADDITIVE PRO	BING FABRICATION UTLITES	MANAGE * NSPECT * SELEC	
↔ BROWSER ●)	ADAPTIVE : ADAPTIN	/E1	ľ	↔ BROWSER ●)		VE1	L	
Yoke - Topology (1) v2	😧 Tool 👩 Geometr	ry 🜈 Heights 🗎 Passes 🚾 Linking		Voke - Topology (1) v2	Tool 🖉 Geomet	ry 💋 Heights 🗎 Passes 📴 Linking	0.0	2
D iiill Named Views	▼ Tool		Z Z Z X	D iill Named Views	Tool	_	Z	X
D Models	Tool	Select	~	D Models	Tool	Select		
👍 🗁 Setups	Coolant	Flood	•	🔺 🗁 Setups	Coolant	Flood	•	
D 🗁 Setup1 💿	▼ Feed & Speed			D 🕑 Setup1 💿	▼ Feed & Speed			
	Spindle Speed	5000 rpm	1		Spindle Speed	5000 rpm	:	
	Surface Speed	515.353 ft/min			Surface Speed	515.353 ft/min	1	
	Ramp Spindle Speed	5000 rpm	:		Ramp Spindle Speed	5000 rpm	:	
	Cutting Feedrate	40 in/min	0		Cutting Feedrate	40 in/min	0	
10	Feed per Tooth	0.00266667 in	0		Feed per Tooth	0.00266667 in	0	
	Lead-In Feedrate	40 in/min	:		Lead-In Feedrate	40 in/min	:	
	Lead-Out Feedrate	40 in/min	:		Lead-Out Feedrate	40 in/min	:	
	Ramp Feedrate	13.3333 in/min	:		Ramp Feedrate	13.3333 in/min	:	
	Plunge Feedrate	13.3333 in/min			Plunge Feedrate	13.3333 in/min		
	Feed per Revolution	0.00266667 in			Feed per Revolution	0.00266667 in		
	Shuft & Holder				Shaft & Holder			
	A	ОКСа	ncel		0		OK Cancel	

- With most set ups the goal is to remove as much material as possible and then go in and refine the part with smaller passes. This also means we will usually start with the largest tool and get progressively smaller
- For this job we will start out with a 3D adaptive clearing operation
- (i) All operations will have the same 5 tabs (Tool, Geometry, Heights, Passes, Linking) The information will change depending on operation type.
- Select a tool from the tool library

Step 3 — Tool Tabs - Tool

	🖤 Үоке	- Topology (1) V2" × T	
MILLING TURNING	ADDITIVE PR	DBING FABRICATION UTILITIES	
MANUFACTURE + SETUP + 2D +	S0 € 30 €	CILLING V MULTI-AXIS V ACTONS V MANAGE V	INSPECT * SELECT *
+ BROWSER	ADAPTIVE : ADAPT	IVE1	Y
	Tool Tool Tool	try 🧭 Heights 😸 Passes 🖳 Linking	Z Z X
⊿ 🗁 Setups		#1 - Ø1/2" flat (1/2in Flat - Down Cut Amana Tool 46182-K)	
🔺 🗁 Setup1 💿	Coolant	Disabled	•
T1] Adaptive1	▼ Feed & Speed		
	Spindle Speed	18000 rpm	:
	Surface Speed	2356.19 ft/min	:
	Ramp Spindle Speed	18000 rpm	:
	Cutting Feedrate	140 in/min	•
	Feed per Tooth	0.00388889 in	•
	Lead-In Feedrate	50 in/min	*
	Lead-Out Feedrate	50 in/min	*
	Ramp Feedrate	70 in/min	*
	Plunge Feedrate	15 in/min	*
	Feed per Revolution	0.000833333 in	•
	Shaft & Holder		
	0	OK Car	ncel
000000000	A. det the		

- Tool tabs auto fills based on tool library information. For this operation we will be using the 1/2in Flat endmill.
- For this prototype part we are using the MDF tool library
- (i) Feeds & Speeds should be adjusted in this area.
- *i* Hovering over any selection will show a brief description

Step 4 — Tool Tabs - Geometry

	TOKE - TODOLOGY (1) V2"	7
MILLING TURNING	ADDITIVE PROBING FABRICATION UTILITIES	
+ BROWSER	ADAPTIVE : ADAPTIVE1	
▲	💡 Tool 👩 Geometry 👩 Heights 🗎 Passes 🚘 Linking	
D Units: in	▼ Geometry	
Named Views	Machining Boundary None	
∠ B Setups	- 🕅 Stock Contours	
🔺 🗁 Setup1 💿	Stack Collecting	
Discrete Temperature Temperatu	Stock Selections	
	▼ Ø Rest Machining	
	Source From setup stock	
	Adjustment Ignore cusps •	
	Adjustment Offset 0.02 in	
	Tool Orientation	
	Model	
	O OK Cancel	
COMMENTS	ふ. た ゆ った つ:	

- Geometry Tab allows us to select the cutting geometry. For an adaptive clearing it will default to cutting all stock material away.
- If needed containment boundaries can be selected.

Rest(REmaining STock) allows for optimization in later operations. It will calculate what has already been cut. This can decrease machining time however takes much longer to compute



Step 5 — Tool Tabs - Heights

- Heights dictate z restrictions for paths. They can be set higher or lower depending on the operation needs
- Top height and bottom height will be the ones that are most often adjusted.
- (i) Generally there should be some additional stock on the bottom of the part for work holding. This remaining stock can be removed in a 2nd operation or by hand or during a final operation.
- (i) Height plans can also be manually dragged to the correct height if needed