



Lubricate X and Y Axis

Written By: Thomas James Rotello



Step 1 — Link to KnowledgeBase



- Y-axis: <https://knowledgebase.omax.com/protomax/...>
- X-axis: <https://knowledgebase.omax.com/protomax/...>

Step 2 — Record run hours from MAKE in Airtable



- Go to: MAKE > System Status > Sensor Dashboard
- Add 314 hours from laptop